

State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott McCallum, Governor
Darrell Bazzell, Secretary
Gloria L. McCutcheon, Regional
Director

Southeast Region Headquarters
2300 N. Dr. Martin Luther King, Jr.
Drive
PO Box 12436
Milwaukee, Wisconsin 53212-0436
Telephone 414-263-8500
FAX 414-263-8606
TTY 414-263-8713

March 7, 2002

*Received
March 11, 2002*

Dr. Raymond Pahle
12823 W. Forest Dr.
New Berlin, WI 53151

Page 11

Subject: Final Case Closure, Speedy Lube, 3101 S. 108th St., West Allis, WI
FID#241423600, BRRTS#0341001477.

Dear Dr. Pahle:


On April 25, 2001 your site as described above was reviewed for closure by the Department of Natural Resources. The Department reviews environmental remediation cases for compliance with state laws and standards to maintain consistency in the closure of these cases. On September 11, 2001 you were notified that conditional closure was granted to this case.

On October 17, 22, and 31, 2001, and February 25, 2002 the Department received correspondence indicating that you have complied with the conditions of closure.. Based on the correspondence and data provided, it appears that the Speedy Lube Site meets the screening criteria of s. NR 746.07 or s. NR 746.08, Wis. Adm. Code, and the requirements of ch. NR 726, Wis. Adm. Code. The Speedy Lube Site has been remediated to Department standards in accordance with s. NR 726.05, Wis. Adm. Code. The Department considers this case closed and no further investigation, remediation or other action is required at this time.

Your site will be listed on the DNR Remediation and Redevelopment GIS Registry of Closed Remediation Sites. Information that was submitted with your closure request application will be included on the registry. To review the sites on the GIS Registry web page, visit <http://gomapout.dnr.state.wi.us/org/at/et/geo/gwur/index.htm>

If this is a PECFA site, section 101.143, Wis. Stats., requires that PECFA claimants seeking reimbursement of interest costs, for sites with petroleum contamination, submit a final reimbursement claim within 120 days after they receive a closure letter on their site. For claims not received by the PECFA Program within 120 days of the date of this letter, interest costs after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

Please be aware that this case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety or welfare, or the environment.



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Scott: McCallum, Governor
Darrell Bazzell, Secretary
Gloria L. McCutcheon, Regional
Director

Richard Street Annex
4041 North Richards Street
P.O. Box 12436
Milwaukee, Wisconsin 53212
Telephone 414-229-0800
FAX 414-229-0810

September 11, 2001

Dr. Raymond Pahle
12823 W. Forest Dr.
New Berlin, WI 53151

Subject: Conditional Closure, Speedy Lube, 3101 S. 108th St., West Allis, WI
FID#241423600, BRRTS#0341001477.

Dear Mr. Pahle:

On April 25, 2001, the Remediation and Redevelopment closure committee reviewed your request for closure of the case described above. This committee reviews environmental remediation cases for compliance with state rules and statutes to maintain consistency in the closure of these cases. After careful review of the closure request, the Closure Committee has determined that the groundwater contamination on the site appears to have been investigated and remediated to the extent practicable under site conditions. Your case will be closed under s. NR 726.05, Wis. Adm. Code, if the following conditions are satisfied:

- All monitoring wells and recovery wells at the site must be properly abandoned in compliance with ch. NR 141, Wis. Adm. Code, unless long term groundwater monitoring is going to be conducted. If monitoring wells will not be immediately abandoned because you do not file a groundwater use restriction and future groundwater monitoring is planned, you will need to notify me of your monitoring plans in order to qualify for case closure. Documentation of well abandonment must be submitted to Victoria Stovall, Program Assistant R&R, P.O. Box 12436, Milwaukee, Wisconsin 53212 on Form 3300-5B found at www.dnr.state.wi.us/org/water/dgw/gw/ or provided by the Department of Natural Resources.
- Any remaining waste and/or soil piles generated as part of site investigation or remediation activities must be removed from the site and disposed of or treated in accordance with Department of Natural Resources' rules. Please send a letter advising me that any remaining waste and/or soil piles have been removed once that work is completed.
- Section NR 726.05(2)(b). Wis. Adm. Code, provides that if groundwater contamination exceeds NR 140 enforcement standards when a closure request is submitted, a case may only be closed if a groundwater use restriction is recorded for each property where enforcement standards are exceeded. Therefore, recording the required groundwater use restriction is an option that the Department of Natural Resources can offer to you in order to close this case. If you choose not to accept this option, you may be required to conduct additional groundwater monitoring using existing or additional monitoring wells and may

choose to perform additional investigation and cleanup of the remaining contamination in order to qualify for unconditional closure. However, you should note that additional investigation or cleanup work may not be eligible for reimbursement from the Petroleum Environmental Cleanup Fund Award (PECFA) Program. You should contact the Department of Commerce to determine if the additional work will be eligible for reimbursement.

- If you choose to pursue closure with a groundwater use restriction, you will need to submit a draft groundwater use restriction with a copy of the property deed to me (Richards Street Annex, P.O. Box 12436, Milwaukee, WI 53212) and to Judy Ohm (WDNR –LS, P.O. Box 7921, Madison, WI 53707-5921) for review before the document is signed and recorded. You may find a copy of a model groundwater use restriction for your use at our web site at www.dnr.state.wi.us/org/rr. Once Department of Natural Resources Legal Services has checked your draft document for completeness, you should sign it if you own the property, or have the appropriate property owner sign it, and have it recorded at the County Register of Deeds Office. Then, you must submit a copy of the recorded document, with the recording information stamped on it, to me. Please be aware that if a groundwater use restriction is recorded for the wrong property because of an inaccurate legal description that you have provided, you will be responsible for recording corrected documents at the Register of Deeds Office to correct the problem.
- The closure committee has also required that a deed notice be signed and recorded to give notice of the remaining soil contamination associated with the site. Residual soil contamination remains along the building foundation and the north wall of the soil excavation as indicated in the information submitted to the Department of Natural Resources. If soil in these locations is excavated in the future, the property owner at that time will be required to sample and analyze the excavated soil in order to determine whether the contamination still remains. The owner will also have to properly store, treat, or dispose of any excavated materials, based upon the results of that characterization, and take special precautions during excavation activities to prevent a direct contact threat to humans. The purpose of the notice is to notify all future owners that excavation of the contaminated soil may pose an inhalation or other direct contact hazard at the time of excavation.
- You will need to submit a draft deed notice with a copy of the property deed to me (Richards Street Annex, P.O. Box 12436, Milwaukee, WI 53212) and to Judy Ohm (WDNR –LS, P.O. Box 7921, Madison, WI 53707-5921) for review before the document is signed and recorded. You may find a copy of a model deed notice enclosed for your use at our web site at www.dnr.state.wi.us/org/rr. The required notice may be inserted into a groundwater use restriction document, if both a groundwater use restriction and a deed notice are required for the same property. Once reviewed you should sign it if you own the property, or have the appropriate property owner sign it, and have it recorded at the Milwaukee County Register of Deeds Office. Then, you must submit a copy of the recorded document, with the recording information stamped on it, to me. Please be aware that if a deed notice is recorded for the wrong property because of an inaccurate legal description that you have provided, you will be responsible for recording corrected documents at the Register of Deeds Office to correct the problem.
- There is also residual soil and/or groundwater contamination in a public street or highway right-of-way. You should provide written notification of the presence of residual soil and/or


groundwater contamination to the clerk of the town and county or municipality where the right-of-way is located, and to the municipal department or state agency that maintains the right-of-way. You must also notify the utilities, which are impacted by the contamination at BR-2. Please provide me with a copy of the written notifications.

When the above conditions have been satisfied, please submit a letter to let me know that applicable conditions have been met, and your case will be closed.

Please be aware that the case may be reopened pursuant to s. NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that contamination on or from the site poses a threat to public health, safety, or welfare or to the environment.

We appreciate your efforts to restore the environment at this site. If you have any questions regarding this letter, please contact me at 414-229-0870.

Sincerely,

A handwritten signature in black ink, appearing to read "Barbara G. Grundl".

Barbara G. Grundl, P.G.

Hydrogeologist

Remediation & Redevelopment

cc: Brett Swenson - Singh & Associates, Inc.
SED

Linda L. Gaffney

This Deed, made between

Grantor,

Raymond G. Pable

and

Grantee,

Witnesseth, That the said Grantor, for a valuable consideration

conveys to Grantee the following described real estate in Milwaukee

County, State of Wisconsin:

Part of the Northeast 1/4 of Section 15, Township 6 North, Range 21 East described as follows:

COMMENCING at a point which is 60 feet West of the East line of said 1/4 Section and 60 feet South of the North line of the said 1/4 Section; running thence Southerly on a line 60 feet West and parallel to the East line of the said 1/4 Section, 131.89 feet to a point; thence Westerly and parallel to the North line of the said 1/4 Section, 144.3 feet to a point; thence Northerly and parallel to the East line of the said 1/4 Section, 131.89 feet to a point; and thence Easterly on a line 60 feet South of and parallel to the North line of the said 1/4 Section, 144.3 feet to the place of BEGINNING. Excepting therefrom that part thereof described as follows:

COMMENCING at the Northeast corner of said 1/4 section; thence South 89 degrees 39 minutes 00 seconds West on and along the North line of said 1/4 section, 60.00 feet to a point; thence South 0 degrees 17 minutes 30 seconds West and parallel with the East line of said 1/4 section 60.00 feet to the point of beginning; thence continuing South 0 degrees 17 minutes 30 seconds West 3.00 feet to a point; thence North 44 degrees 49 minutes 39 seconds West 7.05 feet to a point; thence North 89 degrees 39 minutes 00 seconds East and parallel with the North line of said 1/4 section 3.00 feet to the point of BEGINNING.

This is not homestead property.

Together with all and singular the hereditaments and appurtenances thereto belonging And Linda L. Gaffney warrants that the title is good, independent in fee simple and free and clear of encumbrances except municipal and zoning ordinances, recorded easements for public utilities, recorded building and use restrictions and covenants, and general taxes levied in 1983 and thereafter, and will warrant and defend the same.

Dated this 8th day of August

TRANSFER
\$495.00
FEE

(SEAL)

(SEAL)

August 8th 1983

Linda L. Gaffney

(SEAL)

AUTHENTICATION

Signature(s) of Linda L. Gaffney
attest that this is the signature of Linda L. Gaffney
Notary Public, Milwaukee County, Wis.
My Commission is permanent (if not, state expiration date)

TITLE: MEMBER STATE BAR OF WISCONSIN
(if not, authorized by § 706.06, Wis. Stats.)

THIS INSTRUMENT WAS DRAFTED BY
Attorney Kathleen O. Miller

(Signatures may be authenticated or acknowledged both are not necessary.)

System of printing name in any capacity should be typed or printed below their signatures
STATE BAR OF WISCONSIN
FORM No. 1-1981

WARRANTY DEED

ACKNOWLEDGMENT

STATE OF WISCONSIN
Milwaukee County, Wis.
Personally came before me this 8th day of August 1983 the above named Linda L. Gaffney

to me known to be the person who executed the foregoing instrument and acknowledge the same.

Notary Public, Milwaukee County, Wis.
My Commission is permanent (if not, state expiration date)

Wisconsin Legal Blank Co. Inc.
Milwaukee, WI

DOC # 5642783
RECORD 4.00
RTX 495.00

Tax Parcel No: 523-9998

Box 263

REEL 1556 PAGE 892
REGISTER
OF DEEDS





Figure 1. Project Location Map



OWNER

SPEEDY LUBE GAS STATION
3101 SOUTH 108TH STREET,
WEST ALLIS, WISCONSIN 53227

ENGINEER

K. SINGH & ASSOCIATES, INC.,
ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

FIGURE 1. Facility Layout, and Conveyance Pipe Location


DATE May 24, 1991	DRAWN BY D.N.S.	REVISIONS BY	DATE	PROJECT NO.
SCALE 	CHECKED BY	P.N.S.	10/19/92	1092
	P.N.S.	P.N.S.	10/19/92	SHEET NO.
				ONE

Table 2
Summary of Groundwater Quality
At Former Speedy Lube Gas station, 3101 South 108th Street, West Allis, Wisconsin

Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
MW-1	5/9/91	9,100	980	160	1,300		290
	6/1/91	16,000	55	480	2,500		56
	After soil remediation						
	6/16/93	1,500	5.33	2.3	45.2		2.5
	8/16/93	896	21.1	2.67	5.84		1.52
	1/20/94	--	--	--	--		--
	8/2/94	128	15.3	<1.76	<5.42	896	--
	12/2/94	928	6.1	ND	ND	1,120	2.8
	3/24/95	240	<5.0	<5.0	<15	500	0.55
	5/30/95	170	3.3	<1.0	<3.0	440	0.57
	7/6/95	10	2.9	<1.0	<3.0	340	0.43
	8/14/95	53	2.8	<1.0	<3.0	390	0.37
	12/21/95	95	<1.0	<1.0	<3.0	380	0.39
	3/19/96	21	<1.0	<1.0	<3.0	210	0.24
	6/18/96	67	0.94	<1.0	2.0	180	0.32
	9/11/96	17	<0.7	<1	<2	300	0.5
	12/10/96	8.7	<1.0	<1.0	<3.0	210	0.11
	3/21/97	200	1.7	0.36	4.2	130	0.46
	6/16/97	3.8	<0.22	<0.2	<0.23	130	0.12
	12/4/97	2.8	<0.22	<0.2	<0.23	140	NT
	6/22/98	0.77	<0.34	<0.35	<0.98	49	NT
	3/6/00	0.38	<0.34	<0.35	<1	36	NT
	6/8/00	0.88	<0.4	<0.37	<1.4	13	NT
MW-2	5/9/91	460	21	31	130		9.6
	6/1/91	3,800	2	210	370		27
	After soil remediation						
	6/16/93	11.9	2.41	<1	<1		0.49
	8/16/93	1	<1	<1	<1		0.35
	1/20/94	<1.0	<1.0	1.25	<2.0	705	0.412
	8/2/94	0.9	1.38	1.28	4.766	509	--
	12/2/94	ND	ND	ND	ND	50.3	ND
	3/24/95	<1.0	<1.0	<1.0	<3.0	160	0.081
	5/30/95	<1.0	<1.0	<1.0	<3.0	260	0.13
	7/6/95	<1.0	<1.0	<1.0	<3.0	210	0.12
	8/14/95	1.2	<1.0	<1.0	<3.0	260	0.13
	12/21/95	<0.5	<1.0	<1.0	<3.0	68	<0.05
	6/18/96	<0.7	<0.7	<1.0	<2.0	0.84	<0.1
	9/11/96	<0.7	<0.7	<1	<2	44	<0.1
	12/10/96	<0.5	<1.0	<1.0	<3.0	<15	<0.05
	3/21/97	0.14	<0.22	<0.2	<0.23	3.8	<0.05
	6/16/97	0.25	<0.22	<0.2	<0.23	28	<0.05

Table 2
Summary of Groundwater Quality
At Former Speedy Lube Gas station, 3101 South 108th Street, West Allis, Wisconsin

Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
MW-2	3/6/00	<0.32	<0.34	<0.35	<1	49	NT
	6/8/200	<0.39	<0.4	<0.37	<1.4	56	NT
MW-3	5/9/91	< 1	< 1	< 1	< 1		< 0.2
	6/1/91	< 1	2	8	7		0.3
	After soil remediation						
	6/16/93	18.3	15.7	3.62	36.2		0.65
	8/16/93	6.18	5.7	1.87	4.66		0.34
	1/20/94	<1.0	<1.0	<1.0	<2.0	1,380	0.81
	8/2/94	25.5	0.718	5.41	36.06	602	--
	12/2/94	16.7	9.2	2.7	<10.7	673	1
	3/24/95	5.1	<1.0	<1.0	<3.0	670	0.27
	5/30/95	18	26	3.7	14	290	0.58
	7/6/95	1.4	1.1	<1.0	<3.0	470	0.33
	8/14/95	12	13	2	13	480	0.45
	12/21/95	27	<5.0	<5.0	<15	340	0.54
	3/19/96	2.1	<1.0	<1.0	<3.0	430	0.27
	6/18/96	10	4.2	2	4.5	350	0.31
	9/11/96	<0.7	<0.7	<1	<2	530	0.36
	12/10/96	1	<1.0	<1.0	<3.0	520	0.19
	3/21/97	2.3	<0.22	<0.2	0.45	410	0.18
	6/16/97	1.8	<0.22	<0.2	<0.23	310	0.17
	12/4/97	1.5	<1.1	<1.0	<1.2	460	NT
	6/22/98	5.8	4.3	1.1	3.2	140	NT
	12/9/98	5.7	0.52	2.8	<1	170	0.25
MW-4	3/6/00	3	1.3	1.1	2.3	82	NT
	6/8/00	2	1.4	0.91	<1.4	110	NT
	5/9/91	4,100	260	2,100	1,700		110
	6/1/91	6,800	< 1	1,500	2,500		40
	After soil remediation						
	6/16/93	4,090	15.7	8.02	96.7		6.5
	8/16/93	442	3.3	5.8	6.52		1.2
	1/20/94	<1.0	<1.0	<1.0	<2.0	1,060	0.619
	8/2/94	< 2.38	2.84	<3.52	10.84	1,540	--
	12/2/94	142	ND	1.7	ND	1,860	1.6
	3/24/95	86	<1.0	<1.0	<3.0	1,200	0.62
	5/30/95	1,700	<5.0	8.6	<15	1,300	1.5
	7/6/95	33	<1.0	<1.0	<3.0	1,100	0.58
	12/21/95	470	<5.0	<5.0	<15	470	0.99
	6/18/96	850	100	340	400	560	2.1
	9/11/96	8	0.93	<1	6.4	410	0.29
	12/10/96	44	<1.0	<1.0	<3.0	230	0.15
	3/21/97	1,100	7.4	15	73	170	1.4
	6/16/97	190	0.49	0.4	14	140	0.38

Table 2
Summary of Groundwater Quality
At Former Speedy Lube Gas station, 3101 South 108th Street, West Allis, Wisconsin

Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
MW-4	12/4/97	210	0.61	0.51	11	120	NT
	6/22/98	11	0.36	<0.35	4.3	75	NT
	12/9/98	<i>1.1</i>	0.49	<0.35	<1	93	0.12
	3/6/00	19	0.61	0.56	1.4	89	NT
	6/8/00	<i>0.9</i>	<0.4	<0.37	<1.4	90	NT
MW-5	5/9/91	< 1	< 1	< 1	< 1		< 0.2
	6/1/91	< 1	< 1	< 1	< 1		< 0.2
After soil remediation							
	6/16/93	<i>1.25</i>	< 1	< 1	< 1		0.1
	8/16/93	< 1	< 1	< 1	< 1		0.15
	1/20/94	--	--	--	--	--	--
	8/2/94	0.462	0.15	0.218	<0.542	113	
	12/2/94	ND	ND	ND	ND	107	ND
	3/24/95	<1.0	<1.0	<1.0	<3.0	39	<0.05
	5/30/95	<1.0	<1.0	47	<3.0	<1.0	<0.05
	7/6/95	<1.0	<1.0	<1.0	<3.0	37	<0.05
	8/14/95	<1.0	<1.0	<3.0	<3.0	47	<0.05
	12/21/95	<0.5	<1.0	<1.0	<3.0	37	<0.05
	3/19/96	<0.5	<1.0	<1.0	<3.0	20	<0.05
	6/18/96	<0.7	<0.7	<1.0	<2.0	26	<0.1
	9/11/96	<0.7	<0.7	<1	<2	41	<0.1
	12/10/96	<0.5	<1.0	<1.0	<3.0	42	<0.05
	3/21/97	<0.13	<0.23	<0.2	<0.23	23	<0.05
	6/16/97	<0.13	<0.22	<0.2	<0.23	27	<0.05
	3/6/00	<0.32	<0.34	<0.35	<1	32	NT
	6/8/00	<0.39	<0.4	<0.37	<1.4	40	NT
After soil remediation							
MW-6	12/4/97	<0.13	<0.22	<0.2	<0.23	<0.16	NT
	6/22/98	<0.32	<0.34	<0.35	<0.98	<0.31	NT
	3/6/00	<0.32	<0.34	<0.35	<1	<0.31	NT
	6/8/00	<0.39	<0.4	<0.37	<1.4	<0.47	NT
After soil remediation							
MW-7	12/4/97	<0.13	<0.22	<0.2	<0.23	<0.16	NT
	6/22/98	<0.32	<0.34	<0.35	<0.98	<0.31	NT
	3/6/00	<0.32	<0.34	<0.35	<1	<0.31	NT
	6/8/00	<0.39	<0.4	<0.37	<1.4	<0.47	NT
BR-1	3/6/00	31	5.4	<0.35	<1.30	45	NT
	6/8/00	<i>1.1</i>	<0.4	<0.37	<1.4	26	NT
	11/1/00	7.1	<0.4	<0.37	<1.43	13	NT
	3/28/01	<i>1.0</i>	<0.4	<0.37	<1.4	12	NT
BR-2	3/6/00	33	1.2	<0.35	<0.98	37	NT
	6/8/00	3.2	<0.4	<0.37	<1.4	88	NT

Table 2
Summary of Groundwater Quality
At Former Speedy Lube Gas station, 3101 South 108th Street, West Allis, Wisconsin

Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
BR-2	11/1/00	4.0	<0.4	<0.37	<1.43	91	NT
	3/28/01	1.1	<0.4	<0.37	<1.4	45	NT
BR-3	3/6/00	2.1	<0.34	<0.35	<0.98	69	NT
	6/8/00	0.51	<0.4	<0.37	<1.4	91	NT
	11/1/00	<0.39	<0.4	<0.37	<1.43	100	NT
	3/28/01	<0.39	<0.4	<0.37	<1.4	89	NT
RW-1	1/20/93	225	76	319	804		---
	1/20/93	551	153	1,199	809		---
	1/21/93	1,016	342	2,359	1,670		---
	1/21/93	< 50	< 50	235	536		---
	1/21/93	15,821	10,708	65,378	59,057		---
	2/11/93	13,617	3,333	37,938	17,036		
	7/19/93	121	135	548	1,369		3.47
	9/21/93	1,860	1,210	5,480	16,640		36.5
	1/20/94	--	--	--	--	--	--
	8/2/94	--	--	--	--	--	--
	12/2/94	3,630	1,630	15,000	11,700	381	52
	3/24/95	17,000	13,000	5,900	79,000	5,900	520
	5/30/95	7,500	1,400	13,000	7,600	2,500	46
	7/6/95	Dry	Dry	Dry	Dry	Dry	Dry
	8/14/95	7,000	2,200	13,000	10,000	2,200	46
	12/21/95	6,900	1,900	16,000	13,000	3,000	78
RW-1 abandoned							
After soil remediation							
RW-2	1/18/93	2,426	1,240	6,217	5,219		---
	1/19/93	1,899	860	4,818	3,781		---
	1/19/93	810	769	2,814	2,116		---
	1/20/93	2,117	1,033	5,144	4,493		---
	1/20/93	2,198	1,087	5,516	4,721		---
	2/11/93	29,685	5,926	63,969	30,633		---
	7/19/93	628	1,880	7,840	16,490		39.7
	9/21/93	10,000	2,720	19,300	21,840		79.1
	11/3/93	15,200	3,300	30,700	31,400		94.4
	1/20/94	17,600	4,850	34,600	32,600	7,840	118
	8/2/94	4,010	2,210	11,600	11,410	586	46.5
	12/2/94	3,390	1,510	11,200	8,790	1,540	40
	3/24/95	6,600	1,900	11,000	8,000	2,600	58
	5/30/95	5,900	2,700	15,000	26,000	2,200	125
	7/6/95	5,600	820	9,600	5,000	2,900	NA
	8/14/95	12,000	2,000	23,000	12,000	4,600	64
	12/21/95	460	92	930	530	190	3.4
	3/19/96	620	74	880	620	270	2.9
	6/14/96	450	12	310	380	270	NA

Table 2
Summary of Groundwater Quality
At Former Speedy Lube Gas station, 3101 South 108th Street, West Allis, Wisconsin

Locations	Date	Benzene (ppb)	Ethylbenzene (ppb)	Toluene (ppb)	Total Xylene (ppb)	MTBE (ppb)	GRO (ppm)
RW-2	6/18/96	1,600	230	3,000	3,600	570	13
RW-2	9/11/96	210	7.4	180	250	200	0.86
	12/3/1996*	3.7	2	7.6	16	160	NT
	12/10/96	220	15	180	180	140	1.0
	1/3/1997*	260	14	380	330	110	NT
	2/7/1997*	5.3	0.86	4	11	190	NT
	3/13/1997*	890	150	1,400	980	<3.2	NT
	4/3/97*	260	3.9	230	350	240	NT
	5/1/1997*	350	36	480	300	130	NT
	6/16/97	6,400	800	9,000	5,200	<8.0	34.0
	6/17/1997*	1,100	180	1,300	810	570	NT
	7/17/1997*	540	86	850	450	330	NT
	8/21/1997*	530	86	340	370	340	NT
	10/2/97*	520	90	680	580	230	NT
	11/6/97*	490	75	610	500	180	NT
	12/3/97*	500	88	600	550	180	NT
Groundwater Remedial unit shut down in December 1997							
	6/22/98	3,500	960	3,200	3,200	1100	NT
	12/9/98	3,000	930	3,800	3,000	760	17.0
	3/6/00	13	4.2	4	6	29	NT
	6/8/00	12	2.5	1	<1.4	27	NT
	11/1/00	70	5.3	2.2	2.8	19	NT
	3/28/01	0.61	0.59	0.4	<1.4	11	NT
PAL		0.5	140	200	1,000	12	
ES		5	700	1,000	10,000	60	

Note: PAL - Preventive Action Limit

ES - Enforcement Standard

* - GAC Inlet samples

NA - Not analyzed

Boldface Values = ES exceedance

Italicized Values = PAL exceedance





Figure 2. Groundwater Elevations-March 2001

OWNER
SPEEDY LUBE GAS STATION
3101 South 108th Street
West Allis, Wisconsin 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

DATE	DRAWN BY	REVISIONS BY	DATE	PROJECT NO.
May 24, 1991	D.N.S.			1092
SCALE	CHECKED BY	P.N.S.	10/19/92	SHEET NO.
0 15 30	P.N.S.	M.J.P.	10/2/97	ONE




OWNER
 SPEEDY LUBE GAS STATION
 3101 South 108th Street
 West Allis, Wisconsin 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
 ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
 1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

Figure 3: Potentiometric Surface - Deep Wells (3/28/01)

DATE May 24, 1991	DRAWN BY D.N.S.	REVISIONS BY	DATE	PROJECT NO.
SCALE 0' 15' 30'	CHECKED BY P.N.S.	P.N.S.	10/19/92	1092
		M.J.P.	10/2/97	SHEET NO. ONE



WEST OKLAHOMA AVENUE


SIDE WALK



1V-7

SOUTH 108TH STREET (HWY-100)

SIDE WALK




LEGEND	
○	TEST BORING
●	MONITORING WELL

OWNER
DR. RAYMOND PAHLE
 SPEEDY LUBE GAS STATION
 3101 SOUTH 108TH STREET,
 WEST ALLIS, WISCONSIN 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
 ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
 1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

FIGURE 3. Plan for Geologic Sections

DATE	DRAWN BY	REVISIONS BY	DATE	PROJECT NO.
May 24, 1991	K. S.			1092
SCALE	CHECKED BY			SHEET NO.
0' 10' 20'	V. L. S.	K. S.	05/24/91	ONE
		K. S.	05/24/91	



Note: Groundwater Elevations Measured on 5/9/91

LEGEND


- CL = Silty Clay/Sandy Clay
- SW = Well Graded Sand
- CL-ML = Clayey Silt
- SP-SM = Poorly Graded Sand
- SC = Clayey Sand
- ▽ = Depth to Water in Soil Boring
- ▽ = Depth to Water in Monitoring Well

OWNER
DR. RAYMOND PAHLE
 SPEEDY LUBE GAS STATION
 3101 SOUTH 108TH STREET,
 WEST ALLIS, WISCONSIN 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
 ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
 1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

FIGURE 4. Geologic Section "A-A"

DATE	DRAWN BY	REVISIONS BY	DATE	PROJECT NO.
June 02, 1991	SM			1092
SCALE	CHECKED BY			SHEET NO.
0' 10' 20'	V. L. S.	K.S.	06/23/91	ONE
		K.S.	06/23/91	



Note: Groundwater Elevations Measured on 5/9/91

LEGEND


- CL - Silty Clay/Sandy Clay
- SW - Well Graded Sand s
- CL-ML - Clayey Silt
- SP-SM - Poorly Graded Sand
- SC - Clayey Sand
- ▽ - Depth to Water in Soil Boring
- ▽ - Depth to Water in Monitoring Well

OWNER
DR. RAYMOND PAHLE
 SPEEDY LUBE GAS STATION
 3101 SOUTH 108TH STREET,
 WEST ALLIS, WISCONSIN 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
 ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
 1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

FIGURE 5. Geologic Section "B-B"

DATE June 02, 1991	DRAWN BY S.M.	REVISIONS BY	DATE	PROJECT NO.
SCALE 0' 10' 20'	CHECKED BY V. L. S.	K.S.	06/23/91	1092
		K.S.	06/23/91	SHEET NO. ONE




OWNER
SPEEDY LUBE GAS STATION
3101 SOUTH 10TH STREET,
WEST ALLIS, WISCONSIN 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.,
ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
1135 LEGION DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

Figure 8. Line of Cross Section A-A', B-B', and C-C'


DATE May 24, 1991	DRAWN BY D.N.S.	REVISIONS BY	DATE	PROJECT NO.
SCALE 10' 20'	CHECKED BY P.N.S.	P.N.S.	10/19/92	1092
		P.N.S.	10/19/92	SHEET NO. ONE



Note : For Excavated Area and Recovery System Vertical Scale is Reduced to 4:1

Legend	
	Fill
	CL Silty Clay/Sandy Clay
	CL-ML Clayey Silt
	SC Clayey Sand

Owner Dr. Raymond Pahle Location: Speedy Lube Gas Station 3101 South 108th Street West Allis, WI 53227	Engineer K. SINGH & ASSOCIATES, INC., Engineers & Environmental Management Consultants 1135 Legion Drive, Elm Grove, Wisconsin 53122, (414) 821-1171	Figure 9 - Geologic Section "A-A" (Through Excavated Area #1)		
		Date April 13, 1999 Scale 	Drawn by M.K.J. Checked by P.N.S.	Project no. 1092 Revised by Date



Note : For Excavated Area Vertical Scale is Reduced to 4:1

Legend	
	Fill
	CL Silty Clay/Sandy Clay
	CL-ML Clayey Silt
	SC Clayey Sand

Owner
Dr. Raymond Pahle
Location:
Speedy Lube Gas Station
3101 South 108th Street
West Allis, WI 53227

Engineer
K. SINGH & ASSOCIATES, INC.,
Engineers & Environmental Management Consultants
1135 Legion Drive, Elm Grove, Wisconsin 53122. (414) 821-1171

Figure 10: Geologic Section "B-B" (Through Excavated Area #1 & Area #3)

Date April 14, 1999	Drawn by M.K.J.	Project no. 1092
Scale 	Checked by P.N.S.	Revised by Date

Document Number

GROUNDWATER USE RESTRICTION

Declaration of Restrictions

In re:

COMMENCING at a point which is 60 feet West of the East line of the said ¼ Section and 60 feet South of the North line of the said ¼ Section; running thence Southerly on a line 60 feet west and parallel to the East line of the said ¼ Section, 131.89 feet to a point; thence Westerly and parallel to the North line of the said ¼ Section, 144.3 feet to a point; thence Northerly and parallel to the East line of the said ¼ Section, 131.89 feet to a point; and thence Easterly on a line 60 feet South of and parallel to the North line of the said ¼ Section, 144.3 feet to the place of BEGINNING. Excepting therefrom that part thereof described as follows:

COMMENCING at the Northeast corner of said ¼ section; thence South 89 degrees 59 minutes 00 seconds West on and along the North line of said ¼ section, 60.00 feet to a point; thence South 0 degrees 17 minutes 30 seconds West and parallel with the East line of said ¼ section 60.00 feet to the point of beginning; thence continuing South 0 degrees 17 minutes 30 seconds West 5.00 feet to a point; thence North 44 degrees 49 minutes 39 seconds West 7.05 feet to a point; thence North 89 degrees 59 minutes 00 seconds East and parallel with the North line of said ¼ section 5.00 feet to the point of BEGINNING.

STATE OF WISCONSIN)

) ss

COUNTY OF MILWAUKEE)

8230249

REGISTER'S OFFICE 1 SS
Milwaukee County, WI

RECORDED AT 2:48 PM

02-22-2002

WALTER R. BARCZAK
REGISTER OF DEEDS

AMOUNT 19.00

Recording AreaName and Return Address

K. Singh & Associates, Inc
1135 Legion Drive
Elm Grove, WI 53121

523-9998

Parcel Identification Number (PIN)

WHEREAS, Raymond G. Pahle is the owner of the above-described property.

WHEREAS, One or more petroleum discharges have occurred on this property. Total Petroleum Hydrocarbon Compounds (TPH), Gasoline Range Organic Compounds (GRO), Benzene, Toluene, Ethylbenzene, Xylene, and Methyl-Tert-Butyl Ether (MTBE) contaminated groundwater above ch. NR 140, Wis. Adm. Code, enforcement standards existed on the property at the following location(s) on the following date(s): 16,000 ppb benzene at MW-1 on June 1, 1991, 6,800 ppb benzene at MW-4 on June 1, 1991, 29,685 ppb benzene at RW-2 on February 11, 1993, 88 ppb MTBE at BR-2 on June 8, 2000, and 100 ppb MTBE at BR-3 on November 1, 2000, as shown on Exhibit A, which is attached and hereby make a part of this restriction; and soil contamination existed on the property at the following location(s) on the following date(s): 3,800 ppm TPH in the former gasoline underground storage tank area and 11,000 ppm TPH in the former pump island areas in May 1991, and up to 122.2 ppm GRO along the north side of the building foundation, up to 1,274 ppm GRO along the north excavation wall, and up to 71 ppm GRO along the east excavation wall in September 1992, as shown on Exhibit B, which is attached and hereby make a part of this restriction.

WHEREAS, if the contaminated soil on this property is excavated in the future, it may be considered solid waste and will need to be disposed in accordance with applicable statutes and rules. It is the desire and intention of the property owner to impose on the property restrictions, which will make it unnecessary to conduct further groundwater or soil remediation activities on the property at the present time.

5

WHEREAS, natural attenuation has been approved by the Department of Natural Resources to remediate groundwater contamination exceeding ch. NR 140, Wis. Adm. Code groundwater standards within the boundaries of this property.

WHEREAS, construction of wells where the water quality does not comply with drinking water standards in ch. NR 809 is restricted by chs. NR 811 and NR 812, Wis. Adm. Code. Special well construction standards or water treatment requirements, or both, or well construction prohibitions may apply.

NOW THEREFORE, the owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitation and restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed on this property unless applicable requirements are met.

If construction is proposed on this property that will require dewatering, or if groundwater is to be otherwise extracted from this property, while this groundwater use restriction is in effect, the groundwater shall be sampled and analyzed for contaminants that were previously detected on the property and any extracted groundwater shall be managed in compliance with applicable statutes and rules.

This restriction is hereby declared to be a covenant running with the land and shall be fully binding upon all persons acquiring the above-described property whether by descent, devise, purchase or otherwise. This restriction benefits and is enforceable by the Wisconsin Department of Natural Resources, its successors or assigns. The Department, its successors or assigns, may initiate proceedings at law or in equity against any person or persons who violate or are proposing to violate this covenant, to prevent the proposed violation or to recover damages for such violation.


Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Natural Resources or its successor issue a determination that one or more of the restriction set forth in this covenant is no longer required. Upon the receipt of such a request, the Wisconsin Department of Natural Resources shall determine whether or not the restrictions contained herein can be extinguished. If the Department determines that the restrictions can be extinguished, an affidavit, attached to a copy of the Department's written determination, may be recorded by the property owner or other interested party to give notice that this deed restriction, or portions of this restriction are no longer binding.

3


IN WITNESS WHEREOF, the owner of the property has executed this Declaration of Restriction, this 13 day of Feb 2002

Signature: Raymond G. PahlePrinted Name: Raymond G. PahleTitle: Owner

Subscribed and sworn to before me this 13th day of Feb., 2002.

Marie I. GlaweNotary Public, State of ARIZONAMy commission 14 June 2002

This document was drafted by K. Singh & Associates, Inc., based upon information provided by the Wisconsin Department of Natural Resources.



Note: 01 - Probe Pipe
 02 - Power Line pipe
 03 - Empty Pipe
 04 - Water recovery Pipe
 05 - Water recovery Pipe
 06 - discharge Water pipe

LEGEND


- ▲ Monitoring Well
- Recovery Well
- Blockade

OWNER
 SPEEDY LUBE GAS STATION
 3101 South 108th Street
 West Allis, Wisconsin 53227

ENGINEER
K. SINGH & ASSOCIATES, INC.
 ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
 1135 LIBBY DRIVE, ELM GROVE, WISCONSIN 53122, (414) 821-1171

Exhibit A. Plume of MTBE in Groundwater - Deep Aquifer (3/28/01)

DATE May 24, 1991	DRAWN BY D.N.S.	REVISIONS BY	DATE	PROJECT NO.
SCALE 1" = 25'	CHECKED BY D.N.S.	D.N.S.	10/19/92	1002
		M.E.P.	10/2/97	SUBJECT NO.
				ONE



- Notes: 01 - Probe Pipe
02 - Power Line pipe
03 - Empty Pipe
04 - Water recovery Pipe
05 - Water recovery Pipe
06 - discharge Water pipe

LEGEND

- TEST BORING
● MONITORING WELL
● PROPOSED TEST BORING
● PROPOSED MONITORING WELL

Exhibit B. Facility Layout and Areas of Soil Excavation

DATE	DRAWN BY	REVISIONS BY	DATE	PROJECT NO.
May 24, 1991	D.N.S.			1001
SCALE	CHECKED BY	P.N.S.	10/19/91	SHEET NO.
1" = 10'	P.N.S.	P.N.S.	10/19/91	ONE

OWNER

DR. RAYMOND PAHLE
SPRIDDY LUMB GAS STATION
3164 SOUTH 10TH STREET,
WASHTA COUNTY WISCONSIN 53237

ENGINEER

K. SINGH & ASSOCIATES, INC.,
ENGINEERS & ENVIRONMENTAL MANAGEMENT CONSULTANTS
1135 LEBRON DRIVE, BLM GROVE, WISCONSIN 53122, (414) 833-1171

247598

CERTIFICATE NO. _____

STATE OF WISCONSIN
MILWAUKEE COUNTY

SS.

OFFICE OF
REGISTER OF DEEDS

I, the undersigned,
Register of Deeds of
Milwaukee County,
hereby certify that
this document is a
true and correct copy
of the original on
file or record in
this office.

Witness my hand and
official seal this

FEB 22 2002

Walter A. Barczak
Walter A. Barczak

SEAL

0513189

Document Number

GROUNDWATER USE AND DEED
RESTRICTION

RECORDED ON

In Re Parcel 3: A Piece of Real Estate situated in the South One-Half (1/2) of the South East One-quarter (1/4) of Section numbered Twenty-five (25) in Township numbered Three (3) North, of Range numbered Sixteen (16) East, which piece of real estate is more particularly described as follows, to-wit:

Commencing at a point in the East line of said Section, which point is located 435.6 feet North of the Southeast corner of said Section, thence North in said Section line 200 feet to a point; thence West 300 feet to a point, thence South 200 feet to a point which point is the North West corner of the lands owned by William O'Donnel; thence East in a straight line 300 feet to place of beginning. Subject to water and cesspool rights as per agreement of even date herewith.

2002 JUN 11 AM 9 23

CONNIE J. WOOLEVER
REGISTER OF DEEDS
WALWORTH COUNTY, WI

Recording Area

Name and Return Address

Northern Environmental Technologies, Inc.
1214 West Venture Court
Mequon, Wisconsin 53092 15.00

STATE OF WISCONSIN

)

ss

COUNTY OF

Walworth

G SC2500008E

Parcel Identification Number (PIN)

WHEREAS, Ms. Patricia Sekeres is the owner of the above-described property.

WHEREAS, one or more petroleum discharges have occurred at this property. Groundwater with petroleum contaminated concentrations above ch. NR 140, Wisconsin Administrative Code (Wis. Adm. Code), enforcement standard and soil with contaminant concentrations above ch. NR 720, Wis. Adm. Code, residual contaminant levels are present on the property in the vicinity of the former dispenser islands. The extent of the residual contamination is shown in Figure 3, which is attached and hereby made a part of this restriction.

WHEREAS, it is the desire and intention of the property owner to impose on the property restrictions which will make it unnecessary to conduct further groundwater or soil remediation activities on the property at the present time.

WHEREAS, natural attenuation has been approved by the Department of Natural Resources to remediate groundwater contamination exceeding ch. NR 140, Wis. Adm. Code, groundwater standards within the boundaries of this property.

WHEREAS, construction of wells where the water quality does not comply with drinking water standards in ch. NR 809, Wis. Code, is restricted by chs. NR 811 and NR 812, Wis. Adm. Code. Special well construction standards or water treatment requirements, or both, or well construction prohibitions may apply.

NOW THEREFORE, the owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to construction or reconstructing a well on this property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

109

If construction is proposed on this property that will require dewatering, or if groundwater is to be otherwise extracted from this property, while this groundwater use restriction is in effect, the groundwater shall be sampled and analyzed for contaminants that were previously detected on the property and any extracted groundwater shall be managed in compliance with applicable statutes and rules.

The following activities are prohibited on that portion of the property described above where an asphalt cap or cover has been placed, in the area of the former dispenser islands, unless prior written approval has been obtained from the Wisconsin Department of Natural Resources or its successor or assign: (1) Excavating or grading of the land surface; (2) Filling on the capped area; (3) Plowing for agricultural cultivation; and (4) Construction or installation of a building or other structure with a foundation that would sit on or be placed within the cap or cover. In addition, the cap or cover shall be maintained in compliance with a plan prepared and submitted to the Wisconsin Department of Natural Resources by a responsible party, as required by section NR 724.13(2), Wis. Adm. Code. Also, if the contaminated soil in the area of the former dispenser islands is excavated in the future, it will have to be sampled and analyzed and the treatment or disposal of the soil as a solid or hazardous waste may be necessary.

This restriction is hereby declared to be a covenant running with the land and shall be fully binding upon all persons acquiring the above-described property whether by descent, devise, purchase or otherwise. This restriction inures to the benefit of and is enforceable by the Wisconsin Department of Natural Resources, its successor or assigns. The Department, its successors or assigns, may initiate proceedings at law or in equity against any person or persons who violate or are proposing to violate this covenant, to prevent the proposed violation, or to recover damages for such violation.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.


IN WITNESS WHEREOF, the owner of the property has executed this document, this 28th day of May, 2002.

Signature: Patricia Sekeres
Print Name: Patricia Sekeres

Title: OWNER

Subscribed and sworn to before me
this 28th day of May, 2002

David J. Nommensen
Notary Public, State of Wisconsin
My commission is permanent





This instrument was drafted by: State of Wisconsin Department of Natural Resources

110

LEGEND

- POLE
- ▲ WATER SUPPLY WELL
- ⊠ ELECTRIC BOX
- ⊙ ELECTRICAL OUTLET
- ⊙ SEWER MANHOLE
- ⊗ STREET LIGHT
- STORM SEWER INLET
- MW3 ◆ MONITORING WELL LOCATION AND IDENTIFICATION
- B700 ◆ NORTHERN ENVIRONMENTAL BOREHOLE LOCATION
- STS B2 ◆ STS BOREHOLE LOCATION
- GP5 ◆ ESC BOREHOLE LOCATION
- FORMER USTs AND DISPENSERS
- ⊠ FORMER DISPENSER ISLAND
- G — NATURAL GAS LINE
- - - PROPERTY BOUNDARY
- BILLBOARD
- OE — OVER-HEAD ELECTRIC LINE
- W — WATER MAIN LATERAL
- ST — STORM SEWER LINE
- EXTENT OF RELEASED GASOLINE IN SOIL EXCEEDING NR720 RESIDUAL CONTAMINANT LEVEL STANDARDS
- EXTENT OF RELEASED GASOLINE IN GROUND-WATER EXCEEDING THE ENFORCEMENT STANDARD
- EXTENT OF RELEASED GASOLINE IN SOIL EXCEEDING NR 746.06 TABLE 1 VALVES
- A A' GEOLOGIC CROSS SECTION



DRAWN BY: VLG PROJECT: 01-1408-2204 DATE: 7/13/01

REV. DATE THIS DRAWING AND ALL INFORMATION CONTAINED THEREON IS THE PROPERTY OF NORTHERN ENVIRONMENTAL INCORPORATED AND SHALL NOT BE LOANED, REPRODUCED, COPIED, OR USED EXCEPT FOR THE PROJECT FOR WHICH IT IS EXPRESSLY FURNISHED.

Northern Environmental
Hydrologists • Engineers • Geologists

FORMER SEKERES CITGO
ELKHORN, WISCONSIN

EXTENT OF RELEASED GASOLINE
MAY 8, 2001

FIGURE 3